












Tree ID	Tree Status within ASPECT Studios' documentation	Retention rating (provided by ENSEPC)	Tree Status by ENSEPC	Genus (provided by ENSEPC)	Species (provided by ENSEPC)	Common Name (provided by ENSEPC)	Height (provided by ENSEPC)	Canopy Width (provided by ENSEPC)	Health (provided by ENSEPC)	Life stage (provided by ENSEPC)	Life Expectancy (provided by ENSEPC)	Supplied Photo (provided by ENSEPC)
1	To be Retained Notes: Significant tree	High	Retain	<i>Ulmus</i>	<i>procera</i>	English Elm	18	20	Good	Mature	30-50 years	
2	To be Retained Notes: Significant tree	High	Retain	<i>Ulmus</i>	<i>procera</i>	English Elm	11	13	Good	Mature	30-50 years	
3	To be Retained Notes: Significant tree	High	Retain	<i>Ulmus</i>	<i>procera</i>	English Elm	15	15	Good	Mature	30-50 years	
4	To be Retained Notes: Significant tree	High	Retain	<i>Ulmus</i>	<i>procera</i>	English Elm	16	15	Good	Mature	>50 years	
5	To be Retained Notes: Significant tree	High	Retain	<i>Ulmus</i>	<i>procera</i>	English Elm	18	18	Good	Mature	>50 years	
6	To be Retained Notes: Significant tree	High	Retain	<i>Populus</i>	<i>x canadensis</i>	Canadian Poplar	17	17	Good	Mature	>50 years	
7	Removed (due to Arborist recommendations, due to proposed construction) Notes: Low retention rating within ENSEPC Arboriculture Report. Clash with proposed construction of Rotunda.	Low	Removal	<i>Prunus</i>	<i>serrulata</i>	Japanese Cherry	2	8	Good	Mature	>50 years	

Tree ID	Tree Status within ASPECT Studios' documentation	Retention rating (provided by ENSEPC)	Tree Status by ENSEPC	Genus (provided by ENSEPC)	Species (provided by ENSEPC)	Common Name (provided by ENSEPC)	Height (provided by ENSEPC)	Canopy Width (provided by ENSEPC)	Health (provided by ENSEPC)	Life stage (provided by ENSEPC)	Life Expectancy (provided by ENSEPC)	Supplied Photo (provided by ENSEPC)
8	To be Retained Notes: Significant tree	Moderate	Retain	<i>Salix</i>	<i>X sepulcralis var. chrysocoma</i>	Golden Weeping Willow	14	13	Good	Mature	30-50 years	
9	To be Retained Notes: Significant tree	High	Retain	<i>Populus</i>	<i>x canadensis</i>	Canadian Poplar	18	21	Good	Mature	>50 years	
10	Removed (due to Arborist recommendations, due to design intent) Notes: None retention rating, and low life expectancy (>10 years) within ENSEPC Arboriculture Report, Exotic tree character which does not align with proposed character of landscape works	None	Removal	<i>Pyrus</i>	<i>calleryana cv</i>	Callery Pear variety	7	7	Good	Mature	<10 years	
11	Removed (due to Arborist recommendations, due to design intent) Notes: Low retention rating, and low life expectancy (>10 years) within ENSEPC Arboriculture Report, Exotic tree character which does not align with proposed character of landscape works	Low	Removal	<i>Pyrus</i>	<i>calleryana cv</i>	Callery Pear variety	7	7	Good	Mature	<10 years	
12	Tree to transplanted. Notes: Exotic tree character which does not align with proposed character of landscape works. ASPECT suggest tree be located to north of Lighthouse. DCC to provide comment	Moderate	Removal	<i>Prunus</i>	<i>serrulata</i>	Japanese Cherry	2	10	Good	Mature	>50 years	
13	Removed (due to design intent) Notes: Clash with construction for the Art Axis which provides the major north-south pedestrian movement across the side, from the Rooke Street mall. Exotic tree character which does not align with proposed character of landscape works	Moderate	Removal	<i>Prunus</i>	<i>serrulata</i>	Japanese Cherry	3	11	Good	Mature	>50 years	
14	Removed (due to proposed construction) Notes: Clash with construction of the realignment/upgrade of Formby Road.	Moderate	Removal	<i>Lophostemon</i>	<i>confertus</i>	Brush Box	7	6	Good	Mature	>50 years	

Tree ID	Tree Status within ASPECT Studios' documentation	Retention rating (provided by ENSEPC)	Tree Status by ENSEPC	Genus (provided by ENSEPC)	Species (provided by ENSEPC)	Common Name (provided by ENSEPC)	Height (provided by ENSEPC)	Canopy Width (provided by ENSEPC)	Health (provided by ENSEPC)	Life stage (provided by ENSEPC)	Life Expectancy (provided by ENSEPC)	Supplied Photo (provided by ENSEPC)
15	Removed (due to Arborist recommendations, due to design intent) Notes: None retention rating within ENSEPC Arboriculture Report, clashes with DCC event planning overlay for a clear zone within the 'Common'. Exotic tree character which does not align with proposed character of landscape works	None	Removal	<i>Lagerstroemia</i>	<i>indica</i>	Crepe Myrtle	2	2	Good	Young	>50 years	
16	To be Retained Notes: Native tree character which aligns with proposed character of landscape works	Moderate	Retain	<i>Lophostemon</i>	<i>confertus</i>	Brush Box	8	6	Good	Mature	>50 years	
17	Removed (due to proposed construction) Notes: Clash with construction of the realignment/upgrade of Formby Road.	Moderate	Removal	<i>Tilia</i>	<i>X europaea</i>	Common Linden	8	13	Good	Mature	>50 years	
18	Removed (due to proposed construction) Notes: Clash with construction of the realignment/upgrade of Formby Road.	Moderate	Removal	<i>Tilia</i>	<i>cordata</i>	Small-leaved Linden	8	8	Good	Mature	>50 years	
19	Removed (due to proposed construction) Notes: Clash with construction of the realignment/upgrade of Formby Road.	Moderate	Retain	<i>Lophostemon</i>	<i>confertus</i>	Brush Box	8	7	Good	Mature	>50 years	
20	Removed (due to proposed construction) Notes: Clash with construction of the realignment/upgrade of Formby Road.	Moderate	Removal	<i>Ulmus</i>	<i>glabra Lutescens</i>	Golden Elm	6	7	Good	Mature	30-50 years	
21	Removed (due to proposed construction) Notes: Clash with construction of the realignment/upgrade of Formby Road.	Moderate	Removal	<i>Ulmus</i>	<i>glabra Lutescens</i>	Golden Elm	4	5	Good	Mature	>50 years	

Tree ID	Tree Status within ASPECT Studios' documentation	Retention rating (provided by ENSEPC)	Tree Status by ENSEPC	Genus (provided by ENSEPC)	Species (provided by ENSEPC)	Common Name (provided by ENSEPC)	Height (provided by ENSEPC)	Canopy Width (provided by ENSEPC)	Health (provided by ENSEPC)	Life stage (provided by ENSEPC)	Life Expectancy (provided by ENSEPC)	Supplied Photo (provided by ENSEPC)
22	Removed (due to proposed construction) Notes: Clash with construction of the Elevated Walkway.	Moderate	Removal	<i>Lophostemon</i>	<i>confertus</i>	Brush Box	8	7	Good	Mature	>50 years	
23	Removed (due to proposed construction) Notes: Clash with construction of the realignment/upgrade of Formby Road and of the Elevated Walkway.	Moderate	Removal	<i>Tilia</i>	<i>cordata</i>	Small-leaved Linden	7	11	Good	Mature	>50 years	
24	Removed (due to proposed construction) Notes: Clash with construction of the realignment/upgrade of Formby Road and of the Elevated Walkway.	Moderate	Removal	<i>Prunus</i>	<i>serrulata</i>	Japanese Cherry	2	6	Good	Mature	>50 years	
25	To be Retained Notes: Significant tree	High	Removal	<i>Fraxinus</i>	<i>excelsior</i>	Common Ash	12	16	Good	Mature	>50 years	
26	Removed (due to design intent, due to event overlay) Notes: Exotic tree character which does not align with proposed character of landscape works, clashes with DCC event planning overlay for a clear zone within the B25 'Common'.	Moderate	Removal	<i>Prunus</i>	<i>subhirtella</i>	Higan Cherry	2	1	Good	Mature	>50 years	
27	Removed (due to design intent) Notes: Exotic tree character which does not align with proposed character of landscape works.	Moderate	Removal	<i>Prunus</i>	<i>subhirtella</i>	Higan Cherry	2	4	Good	Mature	>50 years	
28	Removed (due to Arborist recommendations & due to proposed construction) Notes: Low retention rating within ENSEPC Arboriculture Report, and clash with construction of the Elevated Walkway.	Low	Removal	<i>Athrotaxis</i>	<i>selaginoides</i>	King Billy Pine	6	4	Declining	Mature	10-30 years	

Tree ID	Tree Status within ASPECT Studios' documentation	Retention rating (provided by ENSEPC)	Tree Status by ENSEPC	Genus (provided by ENSEPC)	Species (provided by ENSEPC)	Common Name (provided by ENSEPC)	Height (provided by ENSEPC)	Canopy Width (provided by ENSEPC)	Health (provided by ENSEPC)	Life stage (provided by ENSEPC)	Life Expectancy (provided by ENSEPC)	Supplied Photo (provided by ENSEPC)
29	Removed (due to proposed construction) Notes: Clash with construction of the Elevated Walkway.	Moderate	Removal	<i>Eucalyptus</i>	<i>globulus</i>	Tasmanian Blue Gum	11	10	Good	Mature	30-50 years	
30	Removed (due to Arborist recommendations & due to proposed construction) Notes: Low retention rating within ENSEPC Arboriculture Report, and clash with construction of the Elevated Walkway.	Low	Removal	<i>Eucalyptus</i>	<i>globulus</i>	Tasmanian Blue Gum	11	8	Good	Mature	10-30 years	
31	Removed (due to Arborist recommendations, due to design intent) Notes: Low retention rating within ENSEPC Arboriculture Report. Exotic tree character which does not align with proposed character of landscape works.	Low	Removal	<i>Platanus</i>	<i>x acerifolia</i>	London Plane	11	11	Good	Mature	30-50 years	
32	To be Retained Notes: No works in close proximity to tree	Low	Retain	<i>Liquidambar</i>	<i>styraciflua</i>	Liquidamber or Sweetgum	7	8	Good	Mature	>50 years	
33	To be Retained Notes: No works in close proximity to tree	Low	Retain	<i>Malus</i>	<i>ioensis</i>	Prairie Crab Apple	2	2	Good	Mature	>50 years	
34	To be Retained Notes: No works in close proximity to tree	Low	Retain	<i>Malus</i>	<i>ioensis</i>	Prairie Crab Apple	2.5	2	Good	Mature	>50 years	
35	To be Retained Notes: No works in close proximity to tree	Low	Retain	<i>Malus</i>	<i>ioensis</i>	Prairie Crab Apple	2	2	Good	Mature	>50 years	

Tree ID	Tree Status within ASPECT Studios' documentation	Retention rating (provided by ENSEPC)	Tree Status by ENSEPC	Genus (provided by ENSEPC)	Species (provided by ENSEPC)	Common Name (provided by ENSEPC)	Height (provided by ENSEPC)	Canopy Width (provided by ENSEPC)	Health (provided by ENSEPC)	Life stage (provided by ENSEPC)	Life Expectancy (provided by ENSEPC)	Supplied Photo (provided by ENSEPC)
36	Removed (due to Arborist recommendations & due to proposed construction) Notes: Low retention rating within ENSEPC Arboriculture Report, and clash with proposed accessible walkway adhering to compliant rail crossing standards.	Low	Removal	<i>Malus</i>	<i>ioensis</i>	Prairie Crab Apple	2	1	Good	Young	>50 years	
37	Removed (due to proposed construction) Notes: Clash with proposed accessible walkway adhering to compliant rail crossing standards.	Moderate	Removal	<i>Pyrus</i>	<i>calleryana cv</i>	Callery Pear variety	4	6	Good	Mature	>50 years	
38	Removed (due to Arborist recommendations & due to proposed construction) Notes: Low retention rating within ENSEPC Arboriculture Report, and clash with proposed accessible walkway adhering to compliant rail crossing standards.	Low	Removal	<i>Pyrus</i>	<i>calleryana cv</i>	Callery Pear variety	4	1.5	Good	Young	>50 years	
39	To be Retained Notes: No works in close proximity to tree	Moderate	Retain	<i>Pyrus</i>	<i>ussuriensis</i>	Manchurian Pear	5	9	Good	Mature	30-50 years	
40	To be Retained Notes: No works in close proximity to tree	Moderate	Retain	<i>Pyrus</i>	<i>ussuriensis</i>	Manchurian Pear	5	11	Good	Mature	30-50 years	
41	Tree to be Transplanted Notes: Clash with Shared User Path regrading, as DCC have noted these trees have significant cultural meaning, tree to be transplanted. ASPECT suggest tree be located to north of Lighthouse. DCC to provide comment	Moderate	Transplant	<i>Prunus</i>	<i>subhirtella</i>	Higan Cherry	2	2	Good	Mature	>50 years	
42	Tree to be Transplanted Notes: Clash with Shared User Path regrading, as DCC have noted these trees have significant cultural meaning, tree to be transplanted.	Moderate	Transplant	<i>Prunus</i>	<i>subhirtella</i>	Higan Cherry	2	2	Good	Mature	>50 years	
43	Tree to be Transplanted Notes: Clash with Shared User Path regrading, as DCC have noted these trees have significant cultural meaning, tree to be transplanted. ASPECT suggest tree be located to north of Lighthouse. DCC to provide comment	Moderate	Transplant	<i>Prunus</i>	<i>subhirtella</i>	Higan Cherry	2	2	Good	Mature	>50 years	

Tree ID	Tree Status within ASPECT Studios' documentation	Retention rating (provided by ENSEPC)	Tree Status by ENSEPC	Genus (provided by ENSEPC)	Species (provided by ENSEPC)	Common Name (provided by ENSEPC)	Height (provided by ENSEPC)	Canopy Width (provided by ENSEPC)	Health (provided by ENSEPC)	Life stage (provided by ENSEPC)	Life Expectancy (provided by ENSEPC)	Supplied Photo (provided by ENSEPC)
44	Tree to be Transplanted Notes: Clash with Shared User Path regrading, as DCC have noted these trees have significant cultural meaning, tree to be transplanted.	Moderate	Transplant	<i>Prunus</i>	<i>subhirtella</i>	Higan Cherry	2	3	Good	Mature	>50 years	
45	Tree to be Transplanted Notes: DCC have noted these trees have significant cultural meaning, tree to be transplanted. ASPECT suggest tree be located to north of Lighthouse. DCC to provide comment	Moderate	Transplant	<i>Prunus</i>	<i>subhirtella</i>	Higan Cherry	2	2	Good	Mature	>50 years	
46	Tree to be Transplanted Notes: DCC have noted these trees have significant cultural meaning, tree to be transplanted. ASPECT suggest tree be located to north of Lighthouse. DCC to provide comment	Moderate	Transplant	<i>Prunus</i>	<i>subhirtella</i>	Higan Cherry	2	2	Good	Mature	>50 years	
47	Tree to be Transplanted Notes: Clash with Shared User Path regrading, as DCC have noted these trees have significant cultural meaning, tree to be transplanted. ASPECT suggest tree be located to north of Lighthouse. DCC to provide comment	Moderate	Transplant	<i>Prunus</i>	<i>subhirtella</i>	Higan Cherry	2	3	Good	Mature	>50 years	
48	Tree to be Transplanted Notes: Clash with Shared User Path regrading, as DCC have noted these trees have significant cultural meaning, tree to be transplanted. ASPECT suggest tree be located to north of Lighthouse. DCC to provide comment	Moderate	Transplant	<i>Prunus</i>	<i>subhirtella</i>	Higan Cherry	2	3	Good	Mature	>50 years	
49	Removed (due to Arborist recommendations & due to proposed construction) Notes: Low retention rating within ENSEPC Arboriculture Report, and clash with construction of the new Shared User Path alignment.	Low	Removal	<i>Pyrus</i>	<i>calleryana cv</i>	Callery Pear variety	5	4	Good	Mature	30-50 years	
50	Removed (due to Arborist recommendations & due to proposed construction) Notes: Low retention rating within ENSEPC Arboriculture Report, and clash with construction of the new Shared User Path alignment.	Low	Removal	<i>Pyrus</i>	<i>calleryana cv</i>	Callery Pear variety	5	3	Good	Mature	>50 years	

Tree ID	Tree Status within ASPECT Studios' documentation	Retention rating (provided by ENSEPC)	Tree Status by ENSEPC	Genus (provided by ENSEPC)	Species (provided by ENSEPC)	Common Name (provided by ENSEPC)	Height (provided by ENSEPC)	Canopy Width (provided by ENSEPC)	Health (provided by ENSEPC)	Life stage (provided by ENSEPC)	Life Expectancy (provided by ENSEPC)	Supplied Photo (provided by ENSEPC)
51	Removed (due to Arborist recommendations & due to proposed construction) Notes: Low retention rating within ENSEPC Arboriculture Report, and clash with construction of the new Shared User Path alignment.	Low	Removal	<i>Pyrus</i>	<i>calleryana cv</i>	Callery Pear variety	5	3	Good	Mature	>50 years	
52	Removed (due to Arborist recommendations & due to proposed construction) Notes: Low retention rating within ENSEPC Arboriculture Report, and clash with construction of the new Shared User Path alignment.	Low	Removal	<i>Pyrus</i>	<i>calleryana cv</i>	Callery Pear variety	6	4	Good	Mature	>50 years	
53	Tree to be Transplanted Notes: Tree is noted as Critically Endangered tree species. DCC to put forward preferred location of transplanted tree.	Moderate	Transplant	<i>Wollemia</i>	<i>nobilis</i>	Wollemi Pine	3	1	Good	Young	>50 years	
54	Removed (due to Arborist recommendations & due to proposed construction) Notes: Low retention rating within ENSEPC Arboriculture Report, and clash with construction of the new Shared User Path alignment.	Low	Removal	<i>Pyrus</i>	<i>calleryana cv</i>	Callery Pear variety	6	4	Good	Mature	>50 years	
55	Removed (due to Arborist recommendations & due to proposed construction) Notes: Low retention rating within ENSEPC Arboriculture Report, and clash with construction of the new Shared User Path alignment.	Low	Removal	<i>Pyrus</i>	<i>calleryana cv</i>	Callery Pear variety	6	3	Good	Mature	>50 years	
56	Removed (due to Arborist recommendations & due to proposed construction) Notes: Low retention rating within ENSEPC Arboriculture Report, and clash with construction of the new Shared User Path alignment.	Low	Removal	<i>Pyrus</i>	<i>calleryana cv</i>	Callery Pear variety	7	2	Good	Mature	>50 years	
57	Removed (due to Arborist recommendations & due to proposed construction) Notes: Low retention rating within ENSEPC Arboriculture Report, and clash with construction of the new Shared User Path alignment.	Low	Removal	<i>Pyrus</i>	<i>calleryana cv</i>	Callery Pear variety	5	2	Good	Mature	10-30 years	

Tree ID	Tree Status within ASPECT Studios' documentation	Retention rating (provided by ENSEPC)	Tree Status by ENSEPC	Genus (provided by ENSEPC)	Species (provided by ENSEPC)	Common Name (provided by ENSEPC)	Height (provided by ENSEPC)	Canopy Width (provided by ENSEPC)	Health (provided by ENSEPC)	Life stage (provided by ENSEPC)	Life Expectancy (provided by ENSEPC)	Supplied Photo (provided by ENSEPC)
58	Removed (due to Arborist recommendations & due to proposed construction) Notes: Low retention rating within ENSEPC Arboriculture Report, and clash with construction of the new Shared User Path alignment.	Low	Removal	<i>Pyrus</i>	<i>calleryana cv</i>	Callery Pear variety	6	2	Good	Mature	>50 years	
59	Removed (due to Arborist recommendations, due to design intent) Notes: Low retention rating within ENSEPC Arboriculture Report. Exotic tree character which does not align with proposed character of landscape works.	Low	Removal	<i>Prunus</i>	<i>serrulata</i>	Japanese Cherry	2	2	Good	Mature	>50 years	
60	To be Retained Notes: Tree with long life cycle and large size outside of proposed construction of hardscape area.	Low	Removal	<i>Crataegus</i>	<i>sp.</i>	hawthorn	9	10	Good	Mature	>50 years	
61	Removed (due to design intent) Notes: Exotic tree character which does not align with proposed character of landscape works.	Moderate	Removal	<i>Fraxinus</i>	<i>excelsior Aurea</i>	Golden Ash	7	10	Good	Mature	>50 years	
62	To be Retained Notes: Significant tree	Critical	Retain	<i>Tilia</i>	<i>X europaea</i>	Common Linden	10	13	Good	Mature	>50 years	
63	To be Retained Notes: Significant tree	Critical	Retain	<i>Tilia</i>	<i>X europaea</i>	Common Linden	12	16	Good	Mature	>50 years	
64	Removed (due to proposed construction) Notes: Clash with construction of the realignment/upgrade of Formby Road.	Moderate	Removal	<i>Tilia</i>	<i>cordata</i>	Small-leaved Linden	6	8	Good	Mature	>50 years	
65	Removed (due to Arborist recommendations, due to design intent) Notes: Low retention rating within ENSEPC Arboriculture Report. Exotic tree character which does not align with proposed character of landscape works.	Low	Retain	<i>Agonis</i>	<i>flexuosa</i>	Willow Myrtle	9	7	Good	Mature	>50 years	
[APPENDIX: Devonport Waterfront Park - ExistingTree Retention Plan [17.06.2017]]												
[APPENDIX: Devonport Waterfront Park - Proposed Tree Plan [17.06.2017]]												
[END Landscape Architectural Tree Assessment]												